

## Installation Instructions – STKMLD7


### INSTALLATION NOTES:

**IT IS RECOMMENDED TO PRE DRILL HOLES WHEN ATTACHING THE TRIM AS TO AVOID SPLITTING ANY OF THE MOLDING. USE FINISH NAILS & GLUE. (RENTING A BRAD GUN IS A GOOD IDEA AND YOU WON'T NEED TO PRE-DRILL HOLES.)**

**TOTAL STACK HEIGHT: 6-5/16"**

### INSTALL WALL TO WALL:

1. INSTALL TSTM ON TOP OF CABINET. PULL FORWARD UNTIL YOU HAVE 1 1/4" OF TSTM STICKING OUT PAST FACE FRAME.
2. INSTALL CLEAT 1 1/4" IN ON TOP OF TSTM.
3. INSTALL TF396 TO CLEAT (CUT TO SIZE.)
4. INSTALL CROWN MOLDING (SWVCRM8) (CUT TO SIZE.)
5. INSTALL (ACAM) ONTO TF396 UNDER SWVCRM8 (CUT TO SIZE.)



\* SUPPLIED BY OTHERS.